

### 职业卫生检测报告公示

用人单位名称	玉环东莹塑料加工厂
地址	玉环市大麦屿街道普青工业区
联系人	林莹球
项目组成人员	陈焯真、赖春华
现场调查人员	陈焯真
现场调查时间	2023.07.18
现场采样/检测人员	陈焯真、赖春华
现场采样/检测时间	2023.7.18
用人单位陪同人员	林银球
现场图像	 The '现场图像' (On-site Images) section contains two photographs. The top photograph shows the exterior of a multi-story industrial building with a light-colored facade and dark window frames. A large pink sign with Chinese characters is mounted on the upper part of the building. Two red lanterns hang from the entrance area. The bottom photograph shows the interior of a factory, which is a long, narrow space with a concrete floor. The area is filled with various items, including stacks of cardboard boxes, metal parts, and equipment. A white pillar is visible on the left side, and a blue sign is attached to it. The ceiling has exposed pipes and lights.

